

MST-0421

MWA ASC PCB

Test: I2C verification

Serial number:	002
Tester:	Julian Schneider
Date:	16 Dec 2010

Jig details

Use the I²C to USB Adapter to establish communications between the control PC and target device.

- MWA JIG-004 - I2C to USB Adapter

Test procedure

1. Connect I2C jig and interrogate temperature monitor on PCB.
 - Verify temperature is correct.* - yes
2. Warm and cool temperature monitor
 - Verify readout changes.* - yes

After these tests are completed, install the PCB fully in its housing and install all 8 Ferrite 119-3419 components at R33 locations.

Comments