

MST-0431

MWA dual octal temperature sensor

Test: Voltage and current draw test

Serial number:	002
Tester:	C.D.
Date:	8/12/10

Jig details

Detailed wiring diagrams and jig layout can be found in the following document:

- MWA JIG-007 - MWA Voltage and Current Draw Jig

Test procedure

1. Plug the board into the jig and power it up
 - Check 3.3V appears across pins of P1 on top board 3.28Vdc
 - Check current draw less than 1mA using flying leads and a multimeter 0 mA

Comments