

MST-0422

MWA analogue signal conditioning module

Test: I2C test

Serial number:	002
Tester:	Julian Schneider
Date:	20 Dec 2010

Jig details

Use the I²C to USB Adapter to establish communications between the control PC and target device.

- MWA JIG-004 - I2C to USB Adapter

Test procedure

1. Connect I2C jig and send command sequences to the PIC
 - ***ADDR 0x12 for PSI test jig, 0xFA Test Mode***
Write 0xFA, read 0x12 1 byte and verify attenuator bits cycle
- works
2. If the board was put through temperature cycles then re-test the on-board temperature monitor
 - works***

Comments