

## MST-0431

MWA dual octal temperature sensor

### Test: Voltage and current draw test

Serial number: 001

Tester: C.D.

Date: 7/12/2010

### Jig details

Detailed wiring diagrams and jig layout can be found in the following document:

- MWA JIG-007 - MWA Voltage and Current Draw Jig

### Test procedure

1. Plug the board into the jig and power it up
  - Check 3.3V appears across pins of P1 on top board 3.316 Vol
  - Check current draw less than 1mA using flying leads and a multimeter 0 mA

### Comments